

PUBLIC WORKS DEPARTMENT, HARYANA

O/o Executive Engineer,
Provincial Division No. III, PWD B&R Br., Hisar
Tel. - 01662-239887
Email: pwd-ecpd3-hissar@hry.nic.in

To

The Principal,
St. Joseph's International School,
12 KM Store Hisar-Sirsa Road,
Hisar.

Memo No. 1890 Dated 7/5/2026

Subject:- Request for Renewal of School Building Fitness Certificate.

Reference: Your office letter No.5436/SJIS/ADM/CE/2026 dated 25.03.2026

In reference to your office letter under reference, it is intimated that the school building of St. Joseph's International School, 12 KM Store Hisar-Sirsa Road Hisar has been inspected by the Sub Divisional Engineer, Provincial Sub Division No.VI, P.W.D. B&R Branch, Hisar vis-a-vis the structure safety certificate has also issued by the Structural Engineer, Er. Ramavtar Verma (Civil Engg.) vide their certificate dated 23.04.2026. Inspection has been made based on visual inspection and available documents, the structure comprising 03 floors is found to be satisfactory safe and stable under normal usage condition. No detailed structural analysis or testing has been conducted. The safety of the building is subject to regular upkeep and it is recommended that annual maintenance and periodical repairs be ensured to maintain the structural condition.

As reported and recommended by the Sub Divisional Engineer, this certificate is being issued on the current state of the building as of the inspection date which is valid for a period of one year from the date of issue of this letter.

It is also clarified that this certificate is being issued for general safety purposes only and shall not be used for any legal matters or Court cases.

This is for your information & record.

DA/Nil


Executive Engineer,
Provincial Division No. III,
PWD B&R Branch, Hisar


Endst. No.


Dated:

Copy of the above is forwarded to the Sub Divisional Engineer, Provincial Sub Division No.VI, P.W.D. B&R Branch, Hisar w.r.t. his letter No.272 dated 04.05.2026 for information.


St. Joseph's International School

DA/Nil


Principal


Executive Engineer,
Provincial Division No. III,
PWD B&R Branch, Hisar

St. Joseph's International School


Principal

From Assistant Divisional Fire Officer/Fire Station Officer
MC Hisar

To M/s ST JOSEPH INTERNATIONAL SCHOOL
12 KM STONE HISAR TO SIRSA ROAD HISAR 125047
Memo No. FS/2026/35 dated : 11/03/2026

Subject: Renewal of Fire Safety Certificate Under 15 mtrs. height from the fire Safety Point of View of the Group B-Educational Building at 12 KM STONE HISAR TO SIRSA ROAD HISAR 125047 of ST JOSEPH INTERNATIONAL SCHOOL :

Reference to you online No 060352623000055 dated 13/02/2026 on the subject cited above.

Tower Name	Floor Detail	Height	Ground Coverage
ST JOSEPH INTRNATIONAL SCHOOL	GF+FF+SF	12	8000
Basement Level	Basement Area	Remarks	
0	0	0	

Your site for the Renewal of the Fire Safety Certificate has been inspected by the Team of Fire Station Officers, MC Hisar from fire safety Point of View. The means of escape and Fire Protection system were checked and found as per the National Building Code of India, Part- IV guidelines.

In view of the satisfactory fire protection system / arrangement mentioned as above, this office has no objection for occupation from the Fire Safety point of view, with the following conditions:-

- 1) The owner/occupier shall keep duly trained Fire Staff in all three shifts.
- 2) The Fire Protection System tested during inspection shall be maintained properly & always should be in good working condition.
- 3) If any lapse is found in the fire protection system at the time of inspection or detected during outbreak of fire, action will be taken as per rules against you.
- 4) You are directed to apply for Renewal of Fire Safety Certificate in future before 2 month of expiry of your Fire Safety Certificate.
- 5) The open set back area is not checked at our end as it shall be checked by concerned building department.
- 6) The owner/occupier shall strictly follow the other applicable rules/ regulations/ byelaws laid down regarding fire safety system. If you fail to comply with any of the above terms & conditions you will be liable to be punished as per Section 30,31 & 47 of fire & Emergency Services Act 2022.
- 7) You have to perform quarterly Fire Drill in your building as per NBC with intimation to Fire Department and video graphy evidence to be kept as a record which shall be produced at the time of next Renewal; Officials/Residents/R.W.A. should be mentioned in the drill.
- 8) If the Infringements of Byelaws remains un- noticed the Authority reserves the right to amend the Fire Safety Certificate as and when any such Infringements comes to notice after giving an opportunity of being heard and the Authority shall stand Indemnified against any claim on this account.
- 9) The owner or occupier of the building shall give a self-declaration certificate annually to the effect that the fire fighting system installed in his building is working in good condition and there is no addition/alteration in the building. The Fire Officer may randomly check such building. In case there is any addition/alteration beyond permissible limits under the Haryana Building Code, 2017, the fire safety certificate shall cease to exist and the owner shall apply for approval of revised Fire Fighting Scheme as per the provisions of section 18.

The above Renewal of Fire Safety Certificate is valid for **Three** year from the date of issue of this letter Applying renewal of the same well in time shall be the responsibility of owner/occupier.

Remarks:- OK



St. Joseph's International School

[Signature]
Principal

FSO Hisar

MC Hisar

Exercising the power of Director, Fire Services, Haryana



Subject : **Bacteriological Examination Report of Water Samples**

Circle Hisar Circle

Division Hisar PHED No. 1

Sub Division Hisar PHED No. 5

Lab
No.

5

S.No.	Tested Parameter *	Result (MPN) **	Protocol Used	Potable / Not Potable
Memo No :- 640, Date :- 08/04/2026				
1	Sample ID:-HSR/00060/4/2026 /Sender : ST. JOSEPHS INTERNATIONAL SCHOOL CHIKANWAS HISAR ,Location : , ST. JOSEPHS INTERNATIONAL SCHOOL CHIKANWAS HISAR, Analysis Start/End Date: 06/04/2026 / 08/04/2026, GPS Coordinates: 75.652393 /29.274541			
	Total Coliform per 100 ml	0	IS 15185:2016/APHA 9223B-2023/APHA 9221C-2023	Potable
Abstract Report of Bacteriological Examination Report of Water Sample				
Total Sample		Potable		Not Potable
1		1		0


* Requirement (Acceptable Limit) : Shall not be detectable in any 100 ml sample

** MPN (Most Probable Number) Per 100 ML.

Remarks :-

- * The Results Given above are related to the sample as received and tested in HISAR lab.
- * The test report can't be regenerated in whole or part there of without written permission of Competent Authority.
- * The test report can't be used for any publicity or any legal purpose.
- * Reliability of water sample sample lies with sender/collector of water sample.

Sample analyzed by :



KANCHAN BISHNOI, CHEMIST
PUBLIC HEALTH ENGINEERING DEPARTMENT
DISTRICT WATER TESTING LABORATORY, HISAR
email:-chemist.hisar@phedharyana.gov.in

St. Joseph's International School



Principal